



LinkRunner AT Information

Serial Number 0001742163

MAC 00c017b76bed

Report report

Profile Untitled

Date/Time Recorded

4/6/2020 10:02:43 AM

Connection Results

IPv4/v6 Settings

IPv4: Enabled

IPv6: Disabled

IPv4 Information

Address Used (DHCP)

IP: 010.000.000.082

Subnet: 255.255.255.000

Name	IP	Sent	Rcvd	Min	Max	Avg
DHCP Server	010.000.000.138	80	80	1ms	1ms	1ms
Router	010.000.000.138	80	80	1ms	1ms	1ms
DNS Server	010.000.000.138	80	80	1ms	1ms	1ms

AutoTest Results

Name	IP/Hostname	Port	IPv6	Sent	Rcvd	Min	Max	Avg
Target 1	www.google.com	HTTP	False	22	22	22ms	22ms	22ms



LinkRunner AT Information

Serial Number 0001742163

Report report

Date/Time Recorded

MAC 00c017b76bed

Profile Untitled

4/6/2020 10:02:43 AM

Switch Results

Link Configuration

Rx Pair: All
Link Level: Normal
Polarity: Normal
Advertised Speed: 10/100/1000
Actual Speed: 1000
Advertised Duplex: HDx/FDx
Actual Duplex: FDx
Power Over Ethernet: Present
PoE Voltage: -1V/55V
PoE Required Class: 4 (25.5W)
PoE Received Class: 4 (25,5W)
PoE Pair: 3,6+,1,2-
PSE Type: Type2
PoE LLDP Supported: False
Optical Signal Strength: 0dBm

Security

EAP Type: None

LLDP/EDP/CDP

Type	Name	Slot/Port	Address	VLAN	Voice VLAN
LLDP	axis-acc8ebfd3fd	eth0	010.000.000.019	None	None



LinkRunner AT Information

Serial Number 0001742163

MAC 00c017b76bed

Report report

Profile Untitled

Date/Time Recorded

4/6/2020 10:02:43 AM

Cable Results

Wire Map:	ID	Bad
	1 =	1
	2 =	2
	3 =	3
	4 =	4
	5 =	5
	6 =	6
	7 =	7
	8 =	8

Cable Length:

1,2	0 m
3,6	0 m
4,5	0 m
7,8	0 m

LinkRunner AT Information

Serial Number: 0001742163

Boot Version: 143.1025

MAC: 00c017b76bed

802.1X: Disabled

TruePower™: Enabled

Software Version: 301.626

Xilinx Version: 3.6

Type: 2000

Units: Meter

Fiber Information

Type: Unknown

Vendor: None

Revision Code: None

Serial Number: None